


NO ACTIVE PARTITION

If the PC displays this message.




Hit “Enter”. Use the “Down Arrow” to select “UEFI”




1. Turn off the PC then turn it back on. When this screen is displayed, start hitting the “Delete” Key



Hit “Enter”, then hit “F4”, then hit “Enter” again.



2. Use the Arrow button on the keyboard to highlight “Boot Mode Select”



The system should boot in a normally now.