



Author:	Steve E Johnson II	
Date:	01/22/2018	
File Name:	Restoring a M2/M3 CNC Backup Rev B	

## Restoring a M2/M3 CNC Backup

**Step 1** Click on the **Documents folder**> **Local Disk (C)**> **Program Files (x86)**> **M2 or M3 Measuring Software**. May be listed as **V2** (depending on what version has been purchased with the system).

**Step 2** Click on **mxncoptions\_unlocked.exe**.

**Step 3** In the CNC Options box Click on **Load From File**> Direct the file path to the CNC backup you have chosen either from the **Documents Folder** on the PC or a Backup that may have been sent from a Support Tech.

Libraries/Documents/Public Documents/your system serial number/Factory Backup/your system serial number.par

Select the "File"

Select "Open"

Click **Apply** then Click **Save to Flash**.

**Step 4** While in the same screen - The best method of checking functionality of the machine and if the backup was restored properly is to **Auto Home** the machine. If the machines homing sequence performs properly your Backup Restore worked.